

Henderson, Ginny

From: Henderson, Ginny
Sent: Wednesday, January 23, 2013 9:08 AM
To: 'Judy Weseman'
Cc: Joseph Barkevich; Sally Orcutt; Paul Smith; mlivingston@townofwallace.com
Subject: RE: Town of Wallace December Letter - Notice of Regulatory Cleanup Requirements

Judy,
There were actually several monitoring reports over the last year submitted to the UST Section for the old UST issue near the hangars on the north side of the property on Henderson Field Rd. The supply well was sampled during each of the monitoring events. I put a copy of the most recent monitoring report up in our online database: <https://edm.nc.gov/DENR-Portal/>. You can search using either the Name (Wallace Airport) or the ID number (NONCD0002913) in their respective search fields on the right. There is no need to enter anything into the left hand search fields. The UST here in Wilmington has copies of the previous monitoring reports if you would like to view those. You would contact them to set up a file review. Also for clarification it was TCE not PCE that was detected in the supply well. Let me know if you have any additional questions.

Ginny Henderson, P.G.
Hydrogeologist
North Carolina Dept. of Environment & Natural Resources
Div. of Waste Mgt. - Superfund Section - Inactive Hazardous Sites Branch
Wilmington Regional Office
127 Cardinal Drive Extension
Wilmington, NC 28405
Ph: (910) 796-7340 Fax: (910) 350-2004
ginny.henderson@ncdenr.gov

E-mail correspondence to and from this address may be subject to the North Carolina Public Records Law and may be disclosed to third parties.

From: Judy Weseman [<mailto:jweseman@wkdickson.com>]
Sent: Tuesday, January 22, 2013 2:54 PM
To: Henderson, Ginny
Cc: Paul Smith; mlivingston@townofwallace.com; Joseph Barkevich; Sally Orcutt
Subject: Town of Wallace December Letter - Notice of Regulatory Cleanup Requirements

Ginny,
Thanks for taking my call this morning. I've been doing some digging today to try to get to the results which prompted your letter. I understand that PCE was identified in one of two water wells near the hangar at the Wallace Henderson Field Airport. We have been doing environmental due diligence at both of two home sites which had improperly removed storage tanks from previous use as 2 gas stations. We also are doing an EA for a runway extension of the airport. I have learned that no drinking water well sampling was done as part of the scope of any of this work.

Can you please forward to me the environmental report that shows the testing result so we can better assist the Town in responding to your letter?

Thanks in advance for your assistance.

Judy Weseman, PE
Senior Project Manager